



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

Regulatory Docket File

December 26, 1974

Mr. D. L. Ziemann, Chief
 Operating Reactors - Branch 2
 Directorate of Licensing
 Office of Regulation
 U.S. Atomic Energy Commission
 Washington, D.C. 20545



Subject: Dresden Station Units 2 & 3 Special Report No. 18
 AEC DKT 50-23 and 50-249
 Applicable to Quad-Cities Units 1 & 2
 AEC DKT 50-254 and 50-265

Dear Mr. Ziemann:

Dresden Station Special Report No. 18 Supplement C dated April 10, 1974, was submitted to Mr. D. J. Skovholt. This report described the final corrective measures for eliminating containment pressurization incidents resulting from premature actuation of reactor safety valves. The schedule for completing these corrective measures was also discussed.

Due to changes in refueling outage plans for the four (4) units the safety valve corrective measures have been re-scheduled as follows:

- Dresden Unit 3 - Spring 1975 Refueling Outage
- Quad-Cities Unit 1 - Fall 1975 Refueling Outage
- Dresden Unit 2 - Fall 1975 Refueling Outage
- Quad-Cities Unit 2 - Spring 1976 Refueling Outage


A detailed report describing the proposed safety valve corrective measures was schedule for submittal by January 1, 1975. This report has been delayed slightly; and it will be submitted as part of the Dresden Unit 3 Reload 3 Licensing Submittal by February 1, 1975.

If further schedule changes concerning this matter result, you will be notified promptly.

Very truly yours,

J. S. Abel
 J. S. Abel

13134



8103060685