



Telegram

1974 NOV 23 AM 10:06

VEB052(1058)(1-004826A327)PD 11/23/74 1057

ICS IPMVEIB MVN
02049 TDVE MORRIS IL 84 11-22 406P CST
PMS JAMES G KEPPLER
REGIONAL DIRECTOR
DIRECTORATE OF REGULATORY OPERATIONS REGION 3
WUX US ATOMIC ENERGY COMMISSION
799 ROOSEVELT RD
GLEN ELLYN IL 60137

TELEPHONE NBR. 312-858-2660
TELEPHONED TO Mr Johnson BY JS
DATE DLD 11/25 TIME 1054A
ATTEMPTS TO DELIVER. med
11-23 Del. 1135A da 1152A
11/23 da 1215 PM Bay 1046A

SUBJECT DPR-17 DRESDEN NUCLEAR POWER STATION UNIT 2
THIS WILL CONFIRM A CONVERSATION WITH PHIL JOHNSON
OF YOUR OFFICE AT 1600 HOURS THIS DATE CONCERNING FAILURE OF
ELECTRICAL PENETRATION X-2025 TO PASS LOCAT LEAK RATE TEST DURING
ROUTINE REFUEL OUTAGE SURVEILLANCE. CAUSE OF FAILURE IS UNDER
INVESTIGATION. THERE IS NO LEAKAGE THROUGH THE PENETRATION FORM
DRYWELL TO REACTOR BUILDING BUT LEAKAGE IS APPARANTLY CONFINED.

SF-1201 (RS-69)

TO INNER (DRYWELL SIDE) SEAL LEAKAGE IS SEVEN TIMES LIMIT
FOR PENETRATION

B B STEPHENSON SUPERINTENDENT
DRESDON NUCLEAR POWER STATION
COMMONWEALTH EDISON CO
RR #1
MORRIS IL 60450

NNNN

NOV 27 1974

85-1201 (RS-69)

8103060796