



**Commonwealth Edison**

One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

BBS Ltr. #93-75

Dresden Nuclear Power Station  
R.R. #1  
Morris, IL 60450

February 10, 1975

Docket 50-237 and 50-249

James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

SUBJECT: Compliance with IE Bulletin 74-10B

Dear Mr. Keppler:

Inspection Enforcement Bulletin 74-10B, dated January 27, 1975, requested that the requirement of R.O. Bulletin 74-10A be continued indefinitely. This program has been in effect for Dresden Unit 3 since the receipt of R.O. Bulletin 74-10A.

Dresden Unit 2 has been in a refueling outage since the issuance of Bulletin 74-10A. The requirement of I.E. Bulletin 74-10B will be implemented with the startup of the unit.

R.O. Bulletin 74-10A included a requirement to report the results of the required inspections to your office with a copy to the Assistant Director for Construction and Operations, Directorate of Regulatory Operations. My letter, dated January 14, 1975, was sent directly to the Assistant Director without a copy to you. In order to comply fully with R.O. Bulletin 74-10A, a copy of my January 14, 1975 letter is attached.

Sincerely,

B. B. Stephenson  
Superintendent  
Dresden Nuclear Power Station

BBS:LDB:slb

cc: Assistant Director for Construction & Operations  
Directorate of Regulatory Operations  
File/AEC

Enc.

8103110040

FEB 18 1975