



Telegram

TELEGRAMS (OTHER THAN MONEY ORDERS)

VEB246(1743)

IS PHYSICAL DELIVERY required? (YES-AGENT, NO-ADDRESSEE)
AGENT SECTION PD 05/11/74 ADDRESS SECTION

ICS IPMVEIB MVN

Tr. & Name 315 No. 9471 To RDC By mm

02135 TDVE MORRIS

date dtd 11-03-74 11:30P CDT

PMS MR JAMES G KEPP

Attempts to deliver (Indicate DA or BY)

REGIONAL DIRECTOR

DIRECTORATE OF REGULATORY OPERATIONS

REGION 3 WUX

U S ATOMIC ENERGY COMM.

799 ROOSEVELT RD

GLEN ELYN IL 60137

SUBJECT; DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2

THIS WILL CONFIRM A CONVERSATION WITH MR. F. MAURA OF YOUR OFFICE AT 1415 HOURS THIS DATE CONCERNING FAILURE OF THE DRY WELL EQUIPMENT DRAIN SUMP IN BOARD PRIMARY CONTAINMENT ISOLATION VALVE, AG-2001/5, TO CLOSE DURING ROUTINE QUARTERLY PRIMARY CONTAINMENT ISOLATION VALVE SURVEILANCE. AT THE TIME OF THE OCCURANCE

SF-1201 (RS-89)



Telegram

UNIT 2 WAS IN THE COLD SHUT DOWN CONDITION. HOWEVER, DUE TO THE NATURE OF THE FAILURE, A FAULTY SOLENOID OPERATOR FOR THE VALVE, PROPER FUNCTIONING OF THE VALVE WOULD HAVE BEEN IMPAIRED DURING OPERATION. THIS NOTIFICATION WILL BE FOLLOWED BY A TEN DAY REPORT

W.P. WORDEN, SUPERINTENDENT
DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON

RR 1 8103110777
MORRIS IL

MAR 1 4 1974

Duplicate of 1302

WESTERN UNION INCOMING

BETH
008

Regulatory Docket File

1974 MAR 11 PM 7 16

USAEC HQS GTWN

TLXA203 WAE172(1745)(1-037234C070002)PD 03/11/74 U.S. ATOMIC ENERGY COMM.

ICS IPMVEIB MVN

TWX UNIT

02136 TDVE MORRIS IL 113 03-11 350P CDT

PMS MR J E O'LEARY


DIRECTOR DIRECTORATE OF LICENSING
U S ATOMIC ENERGY COMM WUX

WASH DC 20545

SUBJECT: DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2
THIS WILL CONFIRM A CONVERSATION WITH MR. F. MAURA OF YOUR
OFFICE AT 1415 HOURS THIS DATE CONCERNING FAILURE OF THE DRY WELL
EQUIPMENT DRAIN SUMP IN BOARD PRIMARY CONTAINMENT ISOLATION
VALVE, A0-2001/5, TO CLOSE DURING ROUTINE QUARTERLY PRIMARY
CONTAINMENT ISOLATION VALVE SURVEILANCE. AT THE TIME OF THE OCCURANCE
UNIT 2 WAS IN THE COLD SHUT DOWN CONDITION. HOWEVER, DUE TO
THE NATURE OF THE FAILURE, A FAULTY SOLENOID OPEATOR FOR THE VALVE,
PROPER FUNCTIONING OF THE VALVE WOULD HAV BEEN IMPAIRED DURING
OPERATION. THIS NOTIFICATION WILL BE FOLLOWED BY A TEN DAY REPORT

W.P. WORDEN, SUPERINTENDENT
DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON

RR 1
MORRIS IL
NNNN



USAEC HQS GTWN

650P

WU WSH

Dupe WESTERN UNION INCOMING

13083

8 103110777

2047