




**Commonwealth Edison**  
 Dresden Nuclear Power Station  
 R.R. #1  
 Morris, Illinois 60450  
 Telephone 815/942-2920

*DAB*

February 6, 1981

DJS LTR #81-133



James G. Keppler, Regional Director  
 Directorate of Regulatory Operations - Region III  
 U.S. Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, IL 60137

Reportable Occurrence Report #79-017-01X-3, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(c), abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment. This revision corrects transmittal letter of October 23, 1980 to indicate the proper type of reportable occurrence.

*D. J. Scott*

D. J. Scott  
 Station Superintendent  
 Dresden Nuclear Power Station

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement  
 Director of Management Information & Program Control  
 U.S. NRC, Document Mgt. Branch  
 File/NRC

*A002*  
*s*  
*1/1*

*5* 8108170580

MAR 11 1981