




**Commonwealth Edison**  
 Dresden Nuclear Power Station  
 R.R. #1  
 Morris, Illinois 60450  
 Telephone 815/942-2920

DSB

March 13, 1981

DJS LTR #81-214



James G. Keppler, Regional Director  
 Directorate of Regulatory Operations - Region III  
 U.S. Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, IL 60137

Reportable Occurrence Report #81-13/01T-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(i). Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition.

*D.J. Scott*

D. J. Scott  
 Station Superintendent  
 Dresden Nuclear Power Station

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement  
 Director of Management Information & Program Control  
 U.S. NRC, Document Mgt. Branch  
 File/NRC

A002  
 5  
 1/1

8103180618  
 S

MAR 16 1981