




**Commonwealth Edison**  
One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

*Kepler*

February 11, 1981



Mr. James G. Keppler, Director  
Directorate of Inspection and  
Enforcement - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: Dresden Station Units 2 and 3  
Quad Cities Station Units 1 and 2  
Supplemental Response to IE Bulletin  
80-17 Suppl. No. 4, "Failure of  
Control Rods to Insert During a  
Scram at a BWR"  
NRC Docket Nos. 50-237/249 and  
50-254/265

- References (a): J. G. Keppler letter to C. Reed  
dated December 18, 1980.
- (b): T. J. Rausch letter to J. G. Keppler  
dated February 2, 1981.

Dear Mr. Keppler:

Reference (b) transmitted the Commonwealth Edison Company response to IE Bulletin 80-17 Supplement No. 4 for Dresden Units 2 and 3 and Quad Cities Units 1 and 2. In that response we indicated that certain technical information pertaining to the UT scram discharge volume continuous monitoring systems would be supplied as soon as it became available. This information is contained in the enclosure to this letter.

In response to his telephone request, this information is also being provided to Mr. T. Loomis of the NRC in order to complete his review.

*attachments are available in P III Files*


1 FEB 17 1981

8103200044

Q

Please address any concerns you may have concerning this matter to this office.

Very truly yours,



Thomas J. Rausch  
Nuclear Licensing Administrator  
Special Projects

Enclosure

cc: Director, NRC Office of Inspection  
and Enforcement - w/o Encl.

T. Loomis, USNRC - w/Encl.

RIII Inspector - Dresden - w/o Encl.

RIII Inspector - Quad Cities - w/o Encl.

MAR 16 1981