



**Commonwealth Edison**  
 One First National Plaza, Chicago, Illinois  
 Address Reply to: Post Office Box 767  
 Chicago, Illinois 60690

*Central Files*

RECEIVED DISTRIBUTION SERVICES UNIT

1981 FEB 25 PM 12 53

US NRC DISTRIBUTION SERVICES BRANCH

February 11, 1981

Mr. James G. Keppler, Director  
 Directorate of Inspection and  
 Enforcement - Region III  
 U.S. Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, IL 60137

Subject: Dresden Station Units 2 and 3  
 Quad Cities Station Units 1 and 2  
 Supplemental Response to IE Bulletin  
 80-17 Suppl. No. 4, "Failure of  
 Control Rods to Insert During a  
 Scram at a BWR"  
 NRC Docket Nos. 50-237/249 and  
50-254/265

- References (a): J. G. Keppler letter to C. Reed  
 dated December 18, 1980.
- (b): T. J. Rausch letter to J. G. Keppler  
 dated February 2, 1981.

Dear Mr. Keppler:

Reference (b) transmitted the Commonwealth Edison Company response to IE Bulletin 80-17 Supplement No. 4 for Dresden Units 2 and 3 and Quad Cities Units 1 and 2. In that response we indicated that certain technical information pertaining to the UT scram discharge volume continuous monitoring systems would be supplied as soon as it became available. This information is contained in the enclosure to this letter.

In response to his telephone request, this information is also being provided to Mr. T. Loomis of the NRC in order to complete his review.

*attachments are available in R III Files*

FEB 17 1981

8103200284

Q

Please address any concerns you may have concerning this matter to this office.

Very truly yours,



Thomas J. Rausch  
Nuclear Licensing Administrator  
Special Projects

Enclosure

cc: Director, NRC Office of Inspection  
and Enforcement - w/o Encl.

T. Loomis, USNRC - w/Encl.

RIII Inspector - Dresden - w/o Encl.

RIII Inspector - Quad Cities - w/o Encl.