

WESTERN UNION INCOMING

BeBoG
60-237
50-249

USAEC HQS GTWN

TLXA081 (49)DEA083

Regulatory

File Cy.

DE JLA105 NL RC PDB MORRIS ILL 7

1971 AUG 8 AM 8 10

DR. PETER A MORRIS DIRECTOR DIVN OF REACTOR LICENSING USAEC

WASHDC 20545


U.S. ATOMIC ENERGY COMM.
TW X UNIT

DPR19 AND 25 DRESDEN NUCLEAR POWER STATION UNITS 2 AND 3
THIS WILL CONFIRM CONVERSATION 1430 THIS DATE WITH E A JORDON
REGARDING AN UNPLANNED LIQUID RELEASE OCCURING FROM 0945 TO
1105 THIS DATE REPORTABLE UNDER SECTION 66A3 THIS UNPLANNED
RELEASE OCCURED AS A RESULT OF AN ERROR IN VALVE LINE UP CAUSING
B FLOOR DRAIN SAMPLE TANK RELEASE AT A RATE ESTABLISHED FOR
THE A FLOOR DRAIN SAMPLE TANK PRIOR TO ESTABLISHING THE PROPER
DISCHARGE RATE OF THE B TANK. THE RESULTING ACTIVITY IN THE
DISCHARGE WATER WAS 30 PICOCURIES PER LITER OR 30 PERCENT OF
THE ALLOWABLE. A REVIEW OF FACTORS WHICH CONTRIBUTED TO THE
ERROR IS BEING REVIEWED AND ACTION IS BEING TAKEN TO PREVENT
RECURRENCE

1392

H K HOYT SUPT DRESDEN NUCLEAR POWER STATION

DPR19 25 2 3 1430 0945 1105 66JA3.?



420PP

USAEC HQS GTWN

8103240047

3559

LB