

USAEC HQS GTWN

WU WSH

TLXB105 (43)DEA276

DE JLA194 BS NL PDF MORRIS ILL 15

DR PETER A MORRIS, DIRECTOR

DIVISION OF REACTOR LIS.

US ATOMIC ENERGY COMMISSION WASH DC

THIS IS TO INFORM YOU OF A WIRING ERROR DISCOVERED ON APRIL 4TH 1971 THAT RESULTED IN A PHASE REVERSAL ON THE BACK-UP POWER SUPPLY TO THE REACTOR INJECTION VALVE OF THE LOW PRESSURE COLLANT INJECTION SYSTEM. THIS WOULD HAVE PREVENTED THE SYSTEM FROM OPERATING AS DESIGNED WHEN ON BACK-UP POWER. THE WIRING ERROR WAS CORRECTED IMMEDIATELY. A TEN DAY REPORT AS REQUIRED UNDER SECTION 6.6.B.2 OF THE DPR19 TEH. SPECS. IS BEING PREPARED. AS DISCUSSED ON APRIL 14, 1971 WITH G. FIORELLI OF REGION 3 COMPLIANCE AND ON APRIL 15, 1971 WITH R. TEDESCO OF DRL A REQUEST IS HEREBY MADE FOR A 7 DAY EXTENTION TO THIS REPORTING REQUIREMENT

H K HOYT SUPT DRESDEN NUCLEAR POWER STATION.

4TH 1971 6.6.B.2 DPR19 14 1971 3 15 1971 DRL 7.

1148P EST

WU WSH+



USAEC HQS GTWN

WESTERN UNION INCOMING

Regulatory

File Cy.

*Be*



WESTERN UNION INCOMING

8103240059

1384

1904

*DL*

50-237  
4 50

REG. COMM.

RECEIVED  
HEADQUARTERS  
MAIL SERVICE SECTION

1971 APR 16 AM 8 52

U. S. ATOMIC ENERGY  
COMMISSION  
WASHINGTON, D. C.

