

MGMCGBA CGO
2-035836E295 10/22/74
ICS IPMBNGZ CSP
81032422920 MGM TDBN MORRIS IL 100 10-22 0528P EDT
ZIP 60137



Mailgram



THIS MAILGRAM WAS TRANSMITTED ELECTRONICALLY BY WESTERN UNION TO A SERVICE CENTER NEAR YOU FOR DELIVERY

JAMES G KEPPLER, REGIONAL DIRECTOR, DIRECTOR OF REGULATORY OPERATIONS,
REGION 3, US ATOMIC ENERGY COMMISSION
799 ROOSEVELT RD
GLEN ELLYN IL 60137

SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2 THIS WILL CONFIRM
A CONVERSATION WITH MR JOHNSON OF YOUR OFFICE AT 1600 HOURS THIS
DATE CONCERNING FAILURE OF 2 BERGEN PATERSON PIPE RESTRAINTS IN
UNIT 2 DRYWELL 2 WEEKS OF OPERATION ON THE SYSTEM PRIOR TO FAILURE
SNUBBERS WERE REPLACED PRIOR TO UNIT START UP FAILURE WAS DISCOVERED
21 OCTOBER 1974 SEAL MATERIAL WAS POLYURETHANE

B STEVENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEALTH
EDDISON CO RURAL ROUTE 1 MORRIS IL 60450

1730 EDT

MGMCGBA CGO

8103240764

OCT 23 1974

FOR REVERSE SIDE FOR WESTERN UNION'S FULL-RATE SERVICE