

James U. Kappier, Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Atomic Energy Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Teletyped: Date 23 Dec 74  
GE 1354  
DC 1335  
By dlh

cc:  
J. F. O'Leary, Director  
Directorate of Licensing  
U.S. Atomic Energy Commission  
Washington, D.C. 20545

SUBJECT: DPR-19, Dresden Nuclear Power Station, Unit 2.

This will confirm a conversation with P JOHNSON of your office at 13:30 hrs this date concerning A FAILURE OF MAINSTREAM DRAIN VALVE MD-2-220-J. THIS VALVE, WHICH IS ONE OF TWO ISOLATION VALVES IN SERIES, WAS DISASSEMBLED AFTER DIFFICULTY WAS EXPERIENCED IN DRAINING THE MAIN STEAM LINES. THE FAILURE WAS CAUSED BY THE DISC LOCKING NUT BACKING OFF AND PREVENTING THE VALVE FROM OPENING. THE ISOLATION FUNCTION OF THE VALVE WAS NOT COMPROMISED.

12/23/74

203  
JP

To Call:  
GE - 5-854-2660x16 (info) - on 6  
DC - 9-1-361-973-16 (auto)  
Station Dist: (original copy)  
Incl. in  
Tel. No.

B. Johnson, Superintendent  
Dresden Nuclear Power Station  
General Edison Company  
R.  
No.  
Tel. No. 5-854-2520/2621x212  
elect. copy: 1362

8103240768