




Commonwealth Edison
 Dresden Nuclear Power Station
 R.R. #1
 Morris, Illinois 60450
 Telephone 815/942-2920

May 21, 1981

DJS LTR #427



James G. Keppler, Regional Director
 Directorate of Regulatory Operations - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

Reportable Occurrence Report #81-13/01T-0, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(1). Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses, in the safety analysis report, or the technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition.

D. J. Scott
 D. J. Scott
 Station Superintendent
 Dresden Nuclear Power Station

DJS/kmj

Enclosure

cc: Director of Inspection & Enforcement
 Director of Management Information & Program Control
 U.S. NRC, Document Mgt. Branch
 File/NRC

A002
S
1/1