

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 I L D R S 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

7 8 9 L 6 0 5 0 0 0 2 3 7 7 0 1 1 4 8 1 8 0 4 2 3 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 During Unit shutdown, while recirculating the condensate system, a 3/4 inch drain
0 3 line downstream of Minimum Flow Line Valve 2-3406-500 separated 2 inches from the
0 4 recirculation piping at a socket weld. The health and safety of the public was not
0 5 jeopardized because all leakage was contained in the Turbine Building Floor Drain
0 6 System. This was the first recorded event of this type at Dresden.

7 8 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 Excessive vibration of the Minimum Flow Line caused the 16 inch long drain line to
1 1 completely break. Drain was temporarily plugged, and will be shortened and capped
1 2 during the present refueling outage. No further action deemed necessary.

7 8 9 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
1 5 H 0 0 0 0 N/A A Abnormal Radwaste Input

7 8 9 ACTIVITY CONTENT RELEASED AMOUNT OF ACTIVITY LOCATION OF RELEASE
1 6 Z Z N/A N/A

7 8 9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
1 7 0 0 0 Z N/A

7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION
1 8 0 0 0 N/A

7 8 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
1 9 Z N/A

7 8 9 PUBLICITY ISSUED DESCRIPTION
2 0 N 8106090520

NAME OF PREPARER G. Bergan

PHONE: X-529

SUPPLEMENT TO DVR

DVR NO.			
STA	UNIT.	YEAR	NO.
D - 12	- 2	- 81	- 5

PART 1	TITLE OF EVENT	OCCURRED	
	3/4" Drain Line Degradation Downstream of 2-3406-500	1/14/81 DATE	2229 TIME
REASON FOR SUPPLEMENTAL REPORT			
To revise docket number from 050-249 to 050-237			
PART 2			
ACCEPTANCE BY STATION REVIEW	<i>J. Brunner</i>	<i>John Wagoner</i>	_____
DATE	4/27/81	7/30/81	_____
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<i>Douglas West</i> STATION SUPERINTENDENT		4/30/81 DATE