



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

March 28, 1983

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Dresden Station Unit 2
Repair Program for the Twelve
Inch Recirculation Riser
Elbow Welds
NRC Docket No. 50-237

Reference (a): B. Rybak letter to H. R. Denton
dated March 18, 1983.

Dear Mr. Denton:

During discussions with your staff on the repair program contained in reference (a) it was requested that we commit to a mid-cycle (9 months + 3 months) ultrasonic inspection on two of the subject welds which had crack indications but were not weld overlayed. By this letter we are committing to perform the mid-cycle inspection.

Please address any questions on this matter to this office. One (1) signed original and forty (40) copies of this letter are enclosed for your use.

Very truly yours,

B. Rybak
Nuclear Licensing Administrator

lm

cc: Resident Inspector - Dresden
R. Gilbert - NRC

A001

6280N

8303310229 830328
PDR ADOCK 05000237
Q PDR