## DEC 6 1983

ARE FRO PILS COPY

Docket No. 50-237

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690

SUBJECT: DRESDEN NUCLEAR POWER STATION, UNIT 2 CONTAINMENT INTEGRATED LEAK RATE TEST FREQUENCY

References:

ces: 1. Letter dated June 13, 1979, from B. B. Stephenson to H. R. Denton

2. Letter dated July 7, 1983, from D. J. Scott to H. R. Denton

Gentlemen:

8312120275 831206

PDR ADOCK 05000237

We have reviewed the results of the Type A, B and C leak rate tests submitted by References 1 and 2. Our review indicates that the last two consecutive Type A tests at Dresden Unit 2 were failures and, pursuant to 10 CFR 50, Appendix J, Section III.A.6.(b), a Type A test should be performed during each plant shutdown for refueling until two consecutive Type A tests meet the acceptance criteria of Appendix J. Accordingly, unless you request and are granted an exemption from this requirement by NRR, we expect you to conduct a Type A test during your upcoming refueling outage.

We will gladly discuss any questions you have concerning this matter.

Sincerely,

12/5/83

"Original signed by R.L. Spessing"

Spessard

12/6 /83

10

IE28

R. L. Spessard, Director Division of Engineering

D. L. Farrar, Director cc: of Nuclear Licensing D. J. Scott, Station Superintendent DMB/Document Control Desk (RIDS) Resident Inspector, RIII Phyllis Dunton, Attorney General's Office, Environmental Control Division Robert A. Gilbert, NRR Francis Jape, RII Walter R. Butler, NRR

RIII R. S.U.

12/ 5/83

----Walker

PDR

Reves/1d

12/5/83