



UNITED STATES
ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE 326-4537

MAY 9 1969

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch
Division of Compliance, Headquarters

DUKE POWER COMPANY (OCONEE 1, 2, 3), LICENSE NOS. CPPR-33, 34, 35,
DOCKET NOS. 50-269, 270, 287

Transmitted herewith for information are Compliance Report Nos. 269,
270, 287/69-3 covering a routine inspection on April 9-11, 1969. One
nonconformance item was identified which relates to inadequate inspection
of Cadwelds. The licensee has already taken precautions to avoid this
problem in the future. A number of significant weaknesses in onsite
quality control were observed. These were discussed with Duke manage-
ment and we believe a satisfactory response was obtained.

F. J. Long
Senior Reactor Inspector

CO:II:FJL

Enclosure:
CO Report Nos. 269, 270, 287/69-3
(Seidle, Swan)

- cc: E. G. Case, DRS
R. S. Boyd, DRL (2)
S. Levine, DRL (6)
D. J. Skovholt, DRL (3)
L. Kornblith, Jr., CO
R. W. Kirkman, CO:I
B. H. Grier, CO:III
D. I. Walker, CO:IV
R. W. Smith, CO:V
REG Files



ML 15203A685

791180054