

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

April 14, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCY -
INCORRECT ROOT FACE ON SKEWED CADWELD SLEEVES (NCR CEB 80-11)

Initial notification of the subject deficiency was made to
R. W. Wright, NRC-OIE, Region II on March 14, 1980. In compliance
with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the
first interim report of the subject deficiency. TVA anticipates
transmitting the final report on or before June 20, 1980. If
you have any questions regarding this subject, please call Jim Domer
at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8019
2/1