

Files

May 28, 1968

THRU : Charles G. Long, Chief, RFB-3/DRL 151
Paul S. Check, Reactor Project Branch No. 3 151
Division of Reactor Licensing

CADWELD SPICING - TURKEY POINT, DOCKET NOS. 50-250/251

In late January 1968, FP&L was cited for nonconformance of Cadweld splices by CO, Region II. This problem (as well as others) was discussed with DRL at a meeting on February 29, 1968. We suggested that a report be written stating the applicant's position and sent directly to Compliance. The report has now come in under a cover letter to P. A. Morris.

I have spoken to Jim O'Reilly, RI&E Branch, CO about this. He has told me that Compliance will assume the responsibility for the review of this document and will take whatever subsequent action is necessary. I offered DRL's assistance, if he should so desire, and in this regard, I have delivered a copy of the report to A. Gluckmann, RT.

Reference document "Report on Criteria for Cadweld Splices," May 1968, submitted by cover letter dated May 21, 1968.

Distribution:

DRL Reading
RFB-3 Reading
J. P. O'Reilly, CO ✓
C. G. Long
P. S. Check

18/RHE 5/31/68
O'R 6/3/68
J.P. 6/3/68
J.P. 7/1/68
LX 6/7/68

8305250001 700209
PDR ADOCK 05000250
A PDR

RFB-3/DRL RFB-3/DRL

PCheck:pt CGLong

5- -68 5- -68

8 112