



Telegram

VEA216(1649)(2-032643E041)PD 02/10/75 AC BOOK NO. 1649 1975 FEB 10 PR 4:04

ICS IPMBNGZ CSP

TELEPHONE NBR 312-858-2660
TELEPHONED TO P 79 BY 50

8159424449 TDBN MORRIS IL 89 02-10 0449 DLTST 2-11 TIME 10:15 A

PMS JAMES G KEPPLER, REGIONAL DIRECTOR, TEMPEX TO DELIVER:

~~DIRECTORATE OF REGULATORY OPERATIONS REGION 3 U.S. ATOMIC ENERGY COMMISSION 799 ROOSEVELT RD~~

GLEN ELLYN IL 60137

SUBJECT: DPR-19, DRESDEN NUCLEAR POWER STATION UNIT II.

THIS WILL CONFIRM THE CONVERSATION WITH MR JOHNSON OF YOUR OFFICE AT 1300 HOURS THIS DATE CONCERNING ADDITIONAL PIPE CRACK FOUND BY ULTRA-SONIC TEST ON CORE SPRAY LOOP A IN THE SECTION OF PIPE DOWN STREAM OF THE MANUEL VALVE IN THE DRYWELL. THE CRACK IS IN WELD 10-25 AT 12 O'CLOCK AND IS APPROXIMATELY .3 INCHES LONG. THIS WILL BE CORRECTED WHEN OTHER CORE SPRAY PIPING IS REPLACED LATER THIS MONTH.

B B STEPHENS SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

COMMON WEALTH EDISON CO RRI MORRIS IL 60450

SF-1201 (R5-69)

FEB 13 1975



Telegram

1975 JAN 24 PH 4:47

VEB247(1729)(2-038374E024)PD 01/24/75 1729

312-858-2660

ICS IPMBNGZ CSP

8159424449 TDBN MORRIS IL 69 01-24 0529P EST

PMS JAMES G KEPPLER, REGIONAL DIRECTOR DIRECTORATE OF REGULATORY

OPERATION-REGION 3 US ATOMIC ENERGY COMMISSION, WUX NO. _____ OPR. NO. _____

799 ROOSEVELT RD

TELEPHONE NBR. _____

GLEN ELLYN IL 60137

TELEPHONED TO *REC* BY *[Signature]*

SUBJECT: DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2. *127* TIME *9:45*

ATTEMPTS TO TELETYPE: *1/25 8a-1216p*

THIS WILL CONFIRM A CONVERSATION WITH MR JOHNSON OF YOUR OFFICE AT 1540 HOURS THIS DATE CONCERNING FAILURE OF MO-2-22301-4 HIGH PRESSURE COOLANT INJECTION STEAM VALVE IN THE MID POSITION DURING MPCV LOGIC TEST 1-23-75. SYSTEM WAS NOT REQUIRED TO BE OPERABLE AT THIS TIME. CAUSE OF FAILURE UNDER INVESTIGATION.

SF-1201 (R5-73) **B** STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION