

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-10
Docket No. 50-237
Docket No. 50-249

As a result of the inspection conducted during the period April 24 through May 9, 1986, and in accordance with the "General Policy and Procedures for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1985), the following violation was identified:

10 CFR 71.5 prohibits transport of any licensed material outside the confines of a plant or other place of use or delivery of licensed material to a carrier for transport unless the licensee complies with applicable regulations of the Department of Transportation in 49 CFR Parts 170-189.

49 CFR 173.475(b) requires that before each shipment of any radioactive materials package, the shipper shall ensure by examination or appropriate tests that the packaging is in unimpaired physical condition.

Contrary to the above, one package delivered to the burial site on March 14, 1986, and one delivered on April 3, 1986, from Dresden Station, were identified by a State of Washington inspector as each having a hole (or holes) in the package; there was no leakage of package contents.

This is a Severity Level IV violation (Supplement V).

The inspection showed that action had been taken to correct the identified violation and to prevent recurrence. Consequently, no reply to the violation is required and we have no further questions regarding this matter.

5-30-86
Dated

W D Shafer
W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection
Branch

8606040243 860530
PDR ADOCK 05000010
PDR