APR 1 3 1990

Docket No. 50-237 Docket No. 50-249

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by S. G. Du Pont, D. E. Hills and B. L. Siegel, of this office on February 21 through April 2, 1990, of activities at Dresden Nuclear Power Station, Units 2 and 3 authorized by Operating Licenses No. DPR-19 and No. DPR-25 and to the discussion of our findings with Mr. E. Eenigenburg and others at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations with NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790, of the Commission's Regulations, a copy of this letter and the enclosure(s) will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Foriginal signed by W.D. Shafer"

CN

W. D. Shafer, Chief Reactor Projects Branch 1

Enclosure: Inspection Report No. 50-237/90009(DRP) No. 50-249/90008(DRP)

See Attached Distribution

RIII	RIII Ond	RIII	RIII	
For Jones/jp 04/12/90	Lerch	Binds	Shafer	
9004240198 PDR ADOCK	900413 0500023 PD0		ATTACHED SH	SHEFI

APR 1 3 1990

Docket No. 50-237 Docket No. 50-249

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by S. G. Du Pont, D. E. Hills of this office and B. L. Siegel, of the Office of Nuclear Reactor Regulation, on February 21 through April 2, 1990, of activities at Dresden Nuclear Power Station, Units 2 and 3 authorized by Operating Licenses No. DPR-19 and No. DPR-25 and to the discussion of our findings with Mr. E. Eenigenburg and others at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations with NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790, of the Commission's Regulations, a copy of this letter and the enclosure(s) will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief Reactor Projects Branch 1

Enclosure: Inspection Report No. 50-237/90009(DRP) No. 50-249/90008(DRP)

See Attached Distribution

RIII	RIII	RIII
Jones/jp 04/ /90	Lerch	Hinds







12

Commonwealth Edison Company

2 APR 1 3 1990

Distribution

٠.

· · ·

cc w/enclosure: T. Kovach, Nuclear Licensing Manager E. D. Eenigenburg, Station Manager DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Richard Hubbard J. W. McCaffrey, Chief, Public Utilities Division LaSalle, SRI Quad Cities, SRI