

Fac. File

OCT 8 1970

DISTRIBUTION:
DRL R/F
Branch R/F
PDR
Fac. File
DJSkovholt, DRL
PAMorris, DRL

Docket Nos. 55-2768, 567, 2796, 573, 686, 2767,
3077, 3076, 2468, & 2653

Mr. H. K. Hoyt, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
R. R. #1
Morris, Illinois 60450

Dear Mr. Hoyt:

We have received and reviewed your letter, dated September 15, 1970 in which you detailed the actions taken by the licensed individuals during the incident at Dresden Unit No. 2 on June 5, 1970.

Based on the information contained therein and a detailed review of the incident report we have determined that in consideration of (1) the performance of the licensed individuals, (2) the circumstances existing during the course of the incident, (3) the authorities and responsibilities delegated to these individuals and (4) the action taken by facility management, including revision of normal and emergency operating procedures and administrative procedures, there is no need for further action by the Commission at this time with respect to individual licensees.

However, we believe that facility management should ensure through a retraining program that the responsible shift personnel remain cognizant of pertinent AEC and facility procedures, rules and regulations, emphasizing those involving their authority and responsibility during back shift operation of the facility. The details of this program, and your evaluation of the results for each individual, should be submitted in applications for renewal of licenses.

Sincerely yours,
ORIGINAL SIGNED BY
P. F. COLLINS
Paul F. Collins, Chief
Operator Licensing Branch
Division of Reactor Licensing

bcc: J. P. O'Reilly, CO

OFFICE ▶	OLB:DRL X7486 <i>PFC</i>	DRL <i>JS</i>	DRL <i>M</i>		
SURNAME ▶	PFCollins;eh	DJSkovholt	PAMorris		
DATE ▶	10/5/70	10/6/70	10/8/70		