

AUG 20 1970

Mr. Harlen K. Hoyt, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
R. R. #1
Morris, Illinois 60450

Dear Mr. Hoyt:

We have reviewed your submittal, Dresden Nuclear Power Station, Unit No. 2 - Special Report of Incident of June 5, 1970, and are concerned that the licensed individuals involved may not have discharged their responsibilities in a sufficiently competent and safe manner.

Pursuant to Section 55.10(b), the Commission may at any time before the expiration of an operator's or senior operator's license, require further information in order to enable it to determine whether further action should be taken.

We will appreciate your providing us with the following information concerning this matter:

1. The names and license numbers of the individuals involved, and the extent of each individual's involvement during the incident. We would suggest supplementing Sections III-A and B of the report by supplying the individual's name(s) where the word operator(s) appears.
2. The individual(s) who made the decision to operate equipment or systems and to disable equipment and systems.
3. Your evaluation of each individual's knowledge of facility procedures, rules and regulations and AEC rules and regulations.

Mr. Harlen K. Hoyt

-2-

AUG 20 1970

- 4. Each individual's compliance with the responsibilities and authority delegated to them by Dresden management.

A prompt reply is requested so that we may evaluate the information and take further action, pursuant to Section 55.31(e), if necessary, prior to the resumption of operations.

Sincerely yours,

ORIGINAL SIGNED BY
P. F. COLLINS

Paul F. Collins, Chief
Operator Licensing Branch
Division of Reactor Licensing

bcc.: R. Engelken, CO

DISTRIBUTION:

PDR

DRL Reading

Branch Reading

Facility File

D. J. Skovholt, DRL

P. A. Morris, DRL

OGC

(SEE PREVIOUS CONCURRENCE SHEET)

OFFICE	OLB: DRL	DRL	OGC	DRL
SURNAME	PFCollins:pf	DJSkovholt	OGC [initials]	PAMorris [initials]
DATE	7/31/70	7/13/70	8/17/70	8/20/70

Mr. Harlen K. Hoyt, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
R. R. #1
Morris, Illinois 60450

Dear Mr. Hoyt:

We have reviewed your submittal, Special Report of Incident of June 5, 1970, and are concerned that the licensed individuals involved may not have discharged their responsibilities in a competent and safe manner.

The Commission may, at any time before the expiration of an operator's or senior operator's license, require further information in order to enable it to determine whether further action should be taken.

We will appreciate your providing us with the following information concerning this matter:

1. The names and license numbers of the individuals involved, and the extent of each individual's involvement during the incident. We would suggest supplementing Sections III-A and B of the report by supplying the individual's name(s) where the word operator(s) appears.
2. The individual(s) who made the decision to operate equipment or systems and to disable equipment and systems.
3. Your evaluation of each individual's knowledge of facility procedures, rules and regulations and AEC rules and regulations.

Mr. Harlen K. Hoyt

-2-

4. Each individual's compliance with the responsibilities and authority delegated to them by Dresden management.

A prompt reply is requested so that we may evaluate the information and take further action, if necessary, prior to the resumption of operations.

Sincerely yours,

Paul F. Collins, Chief
Operator Licensing Branch
Division of Reactor Licensing

DISTRIBUTION:

PDR

DRL Reading


Branch Reading

Facility File

D. J. Skovholt, DRL

P. A. Morris, DRL

OGC

OFFICE ▶	OLB:DRL	DRL	OGC	DRL	
SURNAME ▶	PFCollins:eh	DJSkovholt		PAMorris	
DATE ▶	7/13/70	7/13/70	7/ /70	7/ /70	

AUG 20 1970

Mr. Harlan K. Hoyt, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
R. R. #1
Morris, Illinois 60450

Dear Mr. Hoyt:

We have reviewed your submittal, Dresden Nuclear Power Station, Unit No. 2 - Special Report of Incident of June 5, 1970, and are concerned that the licensed individuals involved may not have discharged their responsibilities in a sufficiently competent and safe manner.

Pursuant to Section 55.10(b), the Commission may at any time before the expiration of an operator's or senior operator's license, require further information in order to enable it to determine whether further action should be taken.

We will appreciate your providing us with the following information concerning this matter:

1. The names and license numbers of the individuals involved, and the extent of each individual's involvement during the incident. We would suggest supplementing Sections III-A and B of the report by supplying the individual's name(s) where the word operator(s) appears.
2. The individual(s) who made the decision to operate equipment or systems and to disable equipment and systems.
3. Your evaluation of each individual's knowledge of facility procedures, rules and regulations and AEC rules and regulations.

OFFICE ▶						
SURNAME ▶						
DATE ▶						

Mr. Harlen K. Hoyt

-2-

AUG 20 1970

- 4. Each individual's compliance with the responsibilities and authority delegated to them by Dresden management.

A prompt reply is requested so that we may evaluate the information and take further action, pursuant to Section 55.31(e), if necessary, prior to the administration of the forthcoming Dresden Unit No. 3 examinations.

Sincerely yours,

ORIGINAL SIGNED BY
P. F. COLLINS

Paul F. Collins, Chief
Operator Licensing Branch
Division of Reactor Licensing

bcc: R. Engelken, CO

DISTRIBUTION:

PDR

DRL Reading

Branch Reading

Facility File

D. J. Skovholt, DRL

P. A. Morris, DRL

OGC

(SEE PREVIOUS CONCURRENCE SHEET)

OFFICE ▶	OLB:DRL	DRL	OGC	DRL		
SURNAME ▶	PFCollins:pf	DJSkovholt		PAMorris		
DATE ▶	7/31/70	7/13/70	8/17/70	8/ /70		