

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-335
 RECIPIENT: O'REILLY, J.P. NOIR2
 ORIGINATOR: SCHMIDT, A.D. EUTFPL
 COMPANY NAME: FL PWR & LIGHT
 SUBJECT:

DOC DATE: 781002
 ACCESSION NBR: 7810120054
 COPIES RECEIVED:
 LTR 3 ENCL 3
 SIZE: 1+2

Forwards LER#78-037/01T-0: During inspec 66 Class I Longitudinal Braces on RAB Ventilation Ducts were found to be missing due to unknown cause. Remaining braces will be installed w/in 1 week.

DISTRIBUTION CODE: A002
 DISTRIBUTION TITLE:
 INCIDENT REPORTS

NAME	ENCL?	FOR ACTION
BR CHIEF	W/4 ENCL	B GRIMES
REG FILE	W/ENCL	ORB#4 BC
NRC PDR	W/ENCL	P ERICKSON
I & E	W/2 ENCL	ORB#4 LA
MIPC	W/3 ENCL	
I & C SYSTEMS BR	W/ENCL	
EMERGENCY PLAN BR	W/ENCL	
NOVAK/CHECK	W/ENCL	
EEB	W/ENCL	
AD FOR ENG	W/ENCL	
PLANT SYSTEMS BR	W/ENCL	
HANAUER	W/ENCL	
AD FOR PLANT SYSTEMS	W/ENCL	
AD FOR SYS & PROJ	W/ENCL	
REACTOR SAFETY BR	W/ENCL	
ENGINEERING BR	W/ENCL	
VOLLMEYER/BUNCH	W/ENCL	
KREGER/J. COLLINS	W/ENCL	
POWER SYS BR	W/ENCL	
K SEYFRIT/IE	W/ENCL	
LPDR	W/ENCL	
NSIC	W/ENCL	
ACRS	W/16 ENCL	

TOTAL NUMBER OF COPIES REQUIRED:
 LTR 44
 ENCL 44

NOTES:

AD 4
 60



October 2, 1978

PRN-LI-78-282

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-37
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: SEPTEMBER 18, 1978

TECHNICAL SPECIFICATION 6.9
VENTILATION RESTRAINTS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide prompt notification of the subject occurrence.

Very truly yours,


A. D. Schmidt
Vice President
Power Resources

WAK/cpc

Attachment

cc: Harold F. Reis, Esquire
Director, Office of Inspection and Enforcement (40)
Director, Office of Management Information and
Program Control (3)

781012 0054