

A0025

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-335 ST LUCIE 1  
RECIPIENT: O'REILLY, J.P.  
ORIGINATOR: SCHMIDT, A.D.  
COMPANY NAME: FLA PWR & LIGHT CO  
SUBJECT:

DOC DATE: 781124  
ACCESSION NBR: 7812050131  
COPIES RECEIVED:  
LTR 1 ENCL 1  
SIZE: 1+2

LER#78-042/01T-0 on 781111: 4 solenoid operated NaOH Addition Sys Valves found de-energized due to failure to replace fuses for valves SE07-1A, 1B, 2A, & 2B during plant heatup & following outage.

DISTRIBUTION CODE: A002  
DISTRIBUTION TITLE:  
INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
<del>REG FILE</del>	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION  
ORB#4 BC  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

TOTAL NUMBER OF COPIES REQUIRED:  
LTR  
ENCL

42  
42

DEC 6 1978

NOTES:

A0 4  
50

076 270



November 24, 1978

PRN-LI-78-344

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-42  
ST. LUCIE UNIT 1  
DATE OF OCCURRENCE: NOVEMBER 11, 1978

TECHNICAL SPECIFICATION 3.6.2.2  
SPRAY ADDITIVE SYSTEM VALVES

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide prompt notification of the subject occurrence.

Very truly yours,

*J.R. Beusen*  
for A. D. Schmidt  
Vice President  
Power Resources

MAS/cpc

Attachment

cc: Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and Program Control (3)  
Harold F. Reis, Esquire  
File 933.1SL

REGULATORY DOCKET FILE

7812050181

REGULATORY DOCKET