



December 14, 1978  
L-78-386

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:RWZ  
50-335/78-25

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

A handwritten signature in cursive script, appearing to read "R. E. Uhrig".

Robert E. Uhrig  
Vice President

REU/MAS/cpc

Attachment

cc: Harold F. Reis, Esquire

790109 0383

780046

OFFICIAL COPY

## ATTACHMENT

Re: RII:RWZ  
50-335/78-25

### Finding

10 CFR 71.12 provides a general license for delivery of licensed material to a carrier for transport in a package for which a certificate of compliance has been issued and requires compliance with the conditions of the certificate. Condition 5.b.2 of Certificate of Compliance No. 9113 specifies maximum weight limitations of the secondary container and contents. 10 CFR 71.54 requires that, prior to each use of a package or cask for shipment, the licensee shall ascertain that the package with its contents meets the requirements of the license.

Contrary to 10 CFR 71.54, on August 29, 1978, the licensee delivered licensed material to a carrier for transport, in a package for which Certificate of Compliance No. 9113 had been issued without determining the weight of the secondary container or its contents, and the package was shipped from the site before this weight was determined.

### Response

The cited shipment of August 29, 1978 was reviewed and the correct weight notation was attached to the records. Full compliance with 10 CFR 71.54 is now being observed.

Procedure HP-40 (Shipping and Receipt of Radioactive Material) is being revised to help prevent recurrence of the finding. Review and approval of the revised procedure will be completed by January 31, 1979.

