



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

APR 14 1979

In Reply Refer To:

RIT-JPO

50-335

Florida Power and Light Company
Advanced Systems and Technology
Attn: Dr. R. E. Uhrig, Vice President
P. O. Box 529100
Miami, Florida 33152


Gentlemen:

Enclosed is IE Bulletin No. 79-06B, which requires action by you with regard to your Combustion Engineering designed pressurized water reactor facility(ies) with an operating license.

Based on our current understanding of the Three Mile Island accident sequence, and discussion with the designer of your pressurized water reactor, we have reason to believe that pressurizer level indication in your facility may not provide reliable information regarding level in the reactor coolant system under certain transient or accident conditions. You should immediately instruct your operating personnel accordingly. In addition you should consider this possibility in responding to the enclosed bulletin.

Should you have any questions regarding this Bulletin or the actions required by you, please contact this office.

Sincerely,


for James P. O'Reilly
Director

Enclosure:
IE Bulletin No. 79-06B

7905040141

AO 2
GD

APR 14 1979

Florida Power and
Light Company

-2-

cc w/encl:
C. M. Wethy, Plant Manager
Post Office Box 128
Ft. Pierce, Florida 33450

Nat Weems, Assistant QA Manager
Post Office Box 128
Ft. Pierce, Florida 33450

