

USNRC REGION II  
ATLANTA, GEORGIA

29 MAY 25 AIO: 50

P. O. Box 529100  
Miami, Florida 33152



May 22, 1979  
L-79-129

*Central File*  
*50-389*

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO  
50-389/IE Bulletin 79-04

Florida Power & Light Company has received the subject Bulletin regarding the use of Velan swing check valves with incorrect weights. No Velan check valves are being supplied for St. Lucie Unit 2.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU:TCG:cf

cc: Robert Lowenstein, Esquire

7906260288 *Ro 2*  
790054 *Q*  
OFFICIAL COPY *60*  
PEOPLE . . . SERVING PEOPLE

