


USNRC REGION II
ATLANTA, GEORGIA

79 JUN 14 AIO: 04



June 11, 1979
L-79-160

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-389
IE Bulletin 79-03

Florida Power & Light Company has reviewed IE Bulletin 79-03, concerning longitudinal weld defects in ASME SA-312 Type 304 stainless steel pipe spools manufactured by Youngstown Welding and Engineering Company.

We have determined that ASME SA-312 Type 304 or other welded pipe (without filler metal) manufactured by Youngstown Welding and Engineering Company is not used or planned for use in safety related systems at St. Lucie Unit 2.

Very truly yours,

J A de Mastroy
for

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU:MAS:cf

cc: Harold F. Reis, Esquire
Office of Inspection and Enforcement,
Division of Reactor Construction Inspection

7907190 583 Q

79060 60
OFFICIAL COPY

PEOPLE ... SERVING PEOPLE

