


USNRC REGION II
ATLANTA, GEORGIA

79 JUN 18 4 9: 04

P. O. Box 529100
Miami, Florida 33152



June 15, 1979
L-79-166

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
Docket 50-389
IE Bulletin 78-05

The following information supplements our June 26, 1978 (L-78-219) response to IE Bulletin 78-05. Florida Power & Light Company (FPL) has determined that GE CR150X auxiliary contact mechanisms are not in use or planned for use in safety related systems in St. Lucie Unit 2.

This completes FPL action in response to IE Bulletin 78-05.

Very truly yours,



Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU:TCG:cf

cc: Harold F. Reis, Esquire

7907310184

750762