

APPENDIX A

NOTICE OF VIOLATION

Florida Power and Light Company  
St. Lucie Unit 1

License No. DPR-67

Based on the NRC inspection June 5-8, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Technical Specification 6.8.1.a written procedures are required to be established, implemented and maintained covering the applicable procedures recommended in Appendix "A" of Regulatory Guide 1.33, November, 1972.

Contrary to the above:

1. Plant Operating Procedure 0410020 "HPSI/LPSI-Normal Operation", Section 8.1 was not followed in that safeguards pumps minimum flow isolation valve MV-3660, required to be locked open, was found open but unlocked on June 7, 1979.
2. Plant Operating Procedure 0420020 "Containment Spray-Initial Valve Alignment", Section 8.1.9 was not followed in that B header eductor inlet valve 07261, required to be locked open, was found open but unlocked on June 7, 1979.

This is an infraction.

79082 00018

