

Hematite Decommissioning Project	Procedure: HDP-PR-FSS-701, Final Status Survey Plan Development		
		Revision: 10	Appendix P-6, Page 1 of 1

**APPENDIX P-6
FSS FIELD LOG**

Survey Area: PSA 01 **Description:** From MH-02 to MH-31.

Survey Unit: 07 **Description:** _____

FSS Field Log:

<u>Date/Time:</u>	<u>Observation or Comment:</u>	<u>Technician</u>
6/7/16 – 7:00	Begin purge of 2360 Z with 43-68 detector for FSS of piping. The sled will be used for this section because a manned entry is not possible as this is a 12” pipe. The weather today is clear and sunny with temperatures in the mid 70’s. The pipe is clean and dry.	JMichel
6/7/16 – 7:45	Perform pre-QC check of 2360 Z with 43-68 detector.	JMichel
6/7/16 –14 :38	Begin taking 3 – 1 minute background measurements in MH-2 at waist level.	JMichel
6/7/16 – 14:43	Begin scanning accessible surfaces of the pipe at a rate of 1”-2” per second. The instrument will be continuously recording for survey stopping at systematic locations for 1 minute readings.	JMichel
6/7/16 – 15:03	Complete scan of pipe section. No anomalous readings were observed.	JMichel
6/7/16 – 15:08	Perform post-QC check of 2360 Z with 43-68 detector.	JMichel