

Central File

PO. BOX 529100, MIAMI, FL 33152

USNRC REGION II
ATLANTA, GA



38-5 AIO: 28

August 31, 1979
L-79-240

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-335
IE Bulletin 79-06C

We have reviewed the subject Bulletin and a response is attached.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/cph

Attachment

cc: Director, Office of Nuclear Reactor Regulation
Director, Office of Inspection and Enforcement
Harold F. Reis, Esquire


A011
2

60

7910010544

790381

PEOPLE...SERVING PEOPLE



ATTACHMENT

Re: RII:JPO
50-335
IE Bulletin 79-06C

SHORT TERM ACTIONS

Item 1

The actions required by Item 1 were taken at St. Lucie Unit 1 effective upon receipt of the Bulletin.

Items 2 and 3

Combustion Engineering reports CEN-115-P (Response to NRC IE Bulletin 79-06C Items 2 and 3 for Combustion Engineering Nuclear Steam Supply Systems) and CEN-115-NP (non-proprietary version of CEN-115-P) have been prepared for forwarding to Mr. Victor Stello of the NRC.

Item 4

The effort to revise emergency procedures covers many issues which are under consideration by the Combustion Engineering Owners Group. The schedule for revision will depend on resolutions forthcoming from discussions between the NRC staff and the Combustion Engineering Owners Group. As more definitive information is generated, it will be made available to the NRC.

Item 5

To be addressed at a later date consistent with the schedule outlined in the Bulletin.

LONG TERM ACTION

Item 1

Based on the analyses reported in CEN-115-P, automatic tripping of the RCP's is not necessarily a required function. The actions taken in response to Short Term Item 1 should be sufficient as an interim measure. We propose that this item be discussed with the NRC staff following their review of CEN-115-P.

