


USNRC REGION II
ATLANTA, GEORGIA

79 SEP 17 A 9: 55



September 14, 1979
L-79-256

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-335
IE BULLETIN 79-06C

Please revise our response to Item 4 of the subject bulletin to read as follows:

Item 4

The Owner's Group effort to revise emergency procedures covers many issues, including operation of the reactor coolant pumps. Combustion Engineering Report CEN-115P, written in response to Items 2 and 3 of the bulletin, is in disagreement with the immediate action 1.A of this bulletin. As an interim measure, the special instructions issued in compliance with Item 1 are considered to be sufficient. Until the differences mentioned above are resolved, no immediate need exists regarding revision of procedures or additional operator training.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/DKJ/pg
Attachment

cc: Harold F. Reis, Esquire

AOI
790393 (5)
7910080 847
PEOPLE ... SERVING PEOPLE

