

U. S. NUCLEAR REGULATORY COMMISSION
ATLANTA, GEORGIA



79 NOV 13 AM 1:13

November 8, 1979
L-79-320

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:PAT-
50-335/79-23

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

J. A. De Mastroy
for

Robert E. Uhrig
Vice President
Advanced Systems & Technology


REU/MAS/cph

Attachment

cc: Harold Reis, Esquire

7 9121 00 453

790502
OFFICIAL COPY



ATTACHMENT

Re: RII:PAT
50-335/79-23

Finding

As required by Technical Specification 6.8.1, written procedures shall be established, implemented and maintained. Procedure H.P. 90, Sections 4.4 and 7.1, require all emergency equipment to be checked and inventoried once every month at selected locations and to use the appropriate inventory list to ensure that proper supplies are present.

Contrary to the above, a review of the site assembly station inventory records on September 12, 1979, indicated that the inventory of emergency items listed on inventory record sheet 2 of 2 (which contains 20 separate items for emergency use) was not performed for the months of January, February and May 1979.

Response

The October inventory of the Site Assembly Station was recorded and indicated a complete inventory of emergency equipment and supplies.

Procedure HP 90, "Emergency Equipment", has been revised to incorporate record sheets 1 and 2 into one record sheet. This will preclude partial loss of the required documented inventory record.

