


NSNRC REG
ATLANTA

13 DEC 14 AIO: 34



December 7, 1979
L-79-342

Mr. J. P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, N.W. Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

RE: RII:ALC
Docket No. 50-389/79-20

Florida Power & Light Company has reviewed the subject inspection report and our response is attached. There is no proprietary information contained in the report.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MV/ah

Attachment

cc: T. E. Burdette
Harold F. Reis, Esquire

8001 030

772

190173

1-1-1



RII:ALC
50-389/79-20

This NRC Inspection resulted in one finding as described below:

Deficiency: As required by Section 8.12.4 of licensee procedure SQP-15 (as partial implementation of the environmental control program defined in Section 30 (2) of the Construction Permit), the licensee is committed to maintain a daily log of site surveillance, findings and environmental protection activities to assure that all construction activities conform to the environmental conditions defined in the Construction Permit.

Contrary to the above, the licensee failed to maintain the daily log during the period October 15-17, 1979 and October 25, 1979.

Response: Florida Power & Light has evaluated this finding and submits the following response:

The daily log that is required to be maintained was not maintained on the referenced dates because the site environmental control engineer was not on site on those days. For days that he is absent, the environmental engineer has been directed to assign a qualified person to maintain the daily log and perform the necessary site surveillance required by the site procedure.

Full compliance with this audit was achieved on November 5, 1979.

