

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Kinnco Services LLC P.O. Box 219 Williamsburg, MI 49690 REPORT NUMBER(S) 2017001		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-19707	4. LICENSE NUMBER(S) 21-21045-01	5. DATE(S) OF INSPECTION June 29, 2017	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Edward F. Harvey	<i>[Signature]</i>	6/29/17
BRANCH CHIEF	Aaron T. McCraw	<i>[Signature]</i> for ATM	7/26/17

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Kinnco Services LLC P.O. Box 219 Williamsburg, MI 49690 REPORT NUMBER(S) 2017001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-19707	4. LICENSE NUMBER(S) 21-21045-01	5. DATE(S) OF INSPECTION June 29, 2017
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS All
--	--------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Don Wainman, RSO	4. TELEPHONE NUMBER (231) 267-5180
---------------------------------	----------------------	---	---

Main Office Inspection Next Inspection Date: June 29, 2022

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine, unannounced inspection of a small oil well piping supply company in Williamsburg, Michigan. The licensee possessed one NDT Systems, Inc. Model 13640B tube wall calibrator to be used for pipe wall thickness measurements. The device was fixed to an immobilized trailer and the licensee has no plans to transport the device. The licensee indicated that the device had only been used approximately once in the past 12 months.

The inspector observed the gauge in its permanent location and noted that security was adequate. All routes of entry to the trailer were secured with locks and the gauge shutter was locked out when not in use. The inspector performed independent surveys, which revealed no readings that would indicate residual contamination or exposures to members of the public in excess of regulatory limits.

The inspector reviewed pertinent documents including leak test records, dosimetry records, and the utilization log with no issues noted.

No violations of NRC requirements were identified during this inspection.

GW for
ATM
7/26/17