


REC'D

DEC 19 11:58



December 15, 1980  
L-80-405


Mr: J. P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:WPK  
St. Lucie Unit 2  
50-389/80-13

Florida Power & Light Company is providing the attached supplemental response to the subject inspection report in accordance with the telephone request by W. P. Kleinsorge to N. T. Weems on November 25, 1980 as documented in your letter dated November 26, 1980.

Very truly yours,

  
Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/TCG/ah

cc: C. R. McFarland, Region II  
Harold F. Reis, Esquire

8101150 595

RII:WPK  
50-389/80-13

A revision has been made to Florida Power & Light Site Quality Procedure #8, Storage and Distribution of Welding Filler Materials, subsequent to the subject inspection. This change permits welders to place welding electrode stubs and damaged electrodes in containers placed at various locations and labeled (SCRAP ELECTRODES AND WELDING STUBS). All damaged electrodes to be discarded shall be bent approximately 90 degrees.

Full compliance with the above change will be achieved by December 15, 1980.

