

31 JAN 5 AM: 00

Central File
JAN 9 PM
U.S. NRC
DISTRIBUTION SERVICES
RESEARCH
December 30, 1980
88-80-4247
SUN

Mr. James P. O'Reilly, Director, Region II
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, N. W., Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII-JPO
50-389
IE Bulletin 80-21

Florida Power & Light Company has reviewed IE Bulletin 80-21 regarding the use of valve parts cast by Malcolm Foundary Company, Inc. While vendor responses received to date have indicated that valves in safety-related systems do not utilize valve parts manufactured by Malcolm, FPL is still awaiting replies from other vendors. A final response may be expected no later than February 16, 1981, upon completion of this investigation.

Very truly yours,



Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/DME/ah

cc: U. S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
Division of Reactor Construction Inspection
Washington, D. C. 20555

Harold F. Reis, Esquire

NO
2

8101270043

Q