

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8103030872 DOC. DATE: 80/07/28 NOTARIZED: NO  
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co.  
 AUTH. NAME: UHRIG, R.E. AUTHOR AFFILIATION: Florida Power & Light Co.  
 RECIP. NAME: O'REILLY, J.P. RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

DOCKET #  
05000389

SUBJECT: Notifies delay in final deficiency report submittal re door frame Nelson stud failures. Final report scheduled for 800930 submittal.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
ACTION:	A/D LICENSNG 04	1	1	YOUNGBLOOD, B 05	1	1
	RUSHBROOK, M. 06	1	1	NERSES, V. 07	1	1
INTERNAL:	AD/RCI/IE 17	1	1	ASLBP/J. HARD	1	1
	D/DIR HUM. FAC 15	1	1	DIR, DIV OF LIC	1	1
	EDO & STAFF 19	1	1	EQUIP QUAL BR 11	1	1
	HYD/GEO BR 22	1	1	I&E 09	1	1
	LIC QUAL BR 12	1	1	MPA 20	1	1
	NRC PDR 02	1	1	OELD 21	1	1
	PROC/TST REV 13	1	1	QA BR 14	1	1
	<u>REG. FILE</u> 01	1	1	RUTHERFORD, W. IE	1	1
	STANDRDS DEV 21	1	1			
EXTERNAL:	ACRS 16	16	16	LPDR 03	1	1
	NSIC 08	1	1			

MAR 04 1981

*mkf*

TOTAL NUMBER OF COPIES REQUIRED: LTR 39 ENCL 30

*CB*



The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by proper documentation and that the books should be kept up-to-date at all times. The second part of the document outlines the various methods used to verify the accuracy of the accounts, including the use of trial balances and the reconciliation of bank statements.

In addition, the document provides a detailed explanation of the double-entry system, which is the foundation of modern accounting. It describes how every transaction is recorded in two accounts, one as a debit and one as a credit, ensuring that the total debits always equal the total credits. This system not only helps in detecting errors but also provides a clear and concise summary of the financial activities of the business.

USNRC REGION II  
ATLANTA, GEORGIA



80 JUL 31 AIO : 20

July 28, 1980  
L-80-239

Mr. James P. O'Reilly, Director Region II  
Office of Inspection and Enforcement  
US Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: RII : JPO  
50 - 389  
DOOR FRAME NELSON STUD FAILURES

Ref: FP&L Letter L-80-127 dated April 21, 1980


Via the referenced letter, FP&L issued an interim deficiency report, pursuant to 10CFR50.55(e) requirements, to the NRC identifying a deviation from a project specification on tornado resistant doors. The letter indicated that a final report was anticipated by July 31, 1980. We are still in the process of collecting data from the door manufacturer and until it is received, we will be unable to complete a final report. Therefore, this letter is to inform you that a final report will be submitted no later than September 30, 1980.

Very truly yours,

Robert E. Uhrig  
Vice President

REU/JRP/ra

cc: Director of Inspection and Enforcement  
US Nuclear Regulatory Commission  
Washington, D.C. 20555



*Boig  
S/10*

8108080 872

5

OFFICIAL COPY

