


April 16, 1981

PRN-LI-81-190

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:



REPORTABLE OCCURRENCE 335-81-15
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: MARCH 23, 1981
TECHNICAL SPECIFICATION 3.3.3.8
PORV FLOW MONITOR FAILURE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

A.D. Schmidt
Vice President
Power Resources

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

810427 0350

A002
S.I.I.

Handwritten marks or scribbles in the top right corner.

