



May 26, 1981

PRN-LI-81-252

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-81-21  
ST. LUCIE UNIT 1  
DATE OF OCCURRENCE: APRIL 24, 1981  
TECHNICAL SPECIFICATION 3.3.1.1  
FAILURE OF "B" CONTAINMENT PRESSURE DETECTOR.

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

*A.D. Schmidt*  
A.D. Schmidt  
Vice President  
Power Resources

PLP/cab

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 SL

*A002  
5/1/1*

8106080 296

