


11 20 81

11 JUN 10 AM 10 02



June 5, 1981  
L-81-238

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 1  
Docket No. 50-335  
Inspection Report 81-09

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PLP/ras

Attachment

cc: Mr. Harold F. Reis, Esquire

8107080482 810707  
PDR ADOCK 05000335  
Q PDR



ATTACHMENT

RE: ST. LUCIE UNIT 1  
DOCKET NO. 50-335  
INSPECTION REPORT 81-09

FINDING:

Florida Power & Light (FP&L) Company's report "Fire Protection - A Reevaluation of Existing Plant Design Features and Administrative Controls" of March 1977, Section 6.2.2 and Table 6-2, indicates the amount of fire hose and other accessories to be stored in the fire hydrant equipment houses located throughout the plant for protection of safety related systems and components.

Contrary to the above, equipment houses FH1 and FH3 were equipped April 8, 1981 with 100 feet of 1 1/2 inch fire hose, whereas Table 6-2 states that 200 feet of 1 1/2 inch fire hose was to be provided.

RESPONSE:

1. Houses FH1 and FH3 now have 200 feet of 1 1/2 inch hose each.
2. People responsible for inventory of fire equipment have received instructions to preclude repetition of this problem.
3. Corrective action was completed on May 20, 1981.