



**Commonwealth Edison**  
 One First National Plaza, Chicago, Illinois  
 Address Reply to: Post Office Box 767  
 Chicago, Illinois 60690

**REGULATORY DOCKET FILE COPY**  
 50-249

June 16, 1978

US NRC  
 DISTRIBUTION SERVICES  
 BRANCH

1978 JUN 21 PM 4 46

RECEIVED DISTRIBUTION  
 SERVICES UNIT

Mr. George E. Lear, Chief  
 Operating Reactors - Branch 3  
 Division of Operating Reactors  
 U.S. Nuclear Regulatory Commission  
 Washington, DC 20555

Subject: Dresden Station Unit 3  
 Feedwater and Control Rod Drive  
 Nozzle Inspection - Winter 1978  
NRC Docket No. 50-249

Reference (a): M. S. Turbak letter to G. E. Lear  
 dated May 15, 1978

Dear Mr. Lear:

Reference (a) transmitted a summary of the results of the Dresden Station Unit 3 Winter 1978 refuel outage Feedwater and Control Rod Drive Nozzle inspections and repairs. It has been noted that the transmittal had an incorrect docket number. The docket number on the letter was 50-254. It should have been 50-249.

Very truly yours,

M. S. Turbak  
 Nuclear Licensing Administrator  
 Boiling Water Reactors

781730042

A024  
 S/O  
 1/0