

October 10, 1972

Docket No. 50-249

Dr. Chester P. Siess  
Chairman, Advisory Committee  
on Reactor Safeguards  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Dr. Siess:

Sixteen (16) copies of the following are transmitted for the  
Committee's information:

Letter from Commonwealth Edison Company dated September 29,  
1972, reporting that the set points of the isolation condenser  
high steam flow switches and the high condensate flow switches  
exceeded the value specified in the Dresden 3 Technical  
Specifications.

TWX from Commonwealth Edison Company dated October 5,  
1972, reporting that the Dresden Unit 3 ECCS 350 psi  
low reactor pressure switches were out of calibration.

Distribution  
✓ Docket File  
Branch Reading

Sincerely,

*Donald J. Skovholt*  
Donald J. Skovholt  
Assistant Director for  
Operating Reactors  
Directorate of Licensing

Enclosures:  
As stated

OFFICE ▶	L:OR <i>END</i>				
SURNAME ▶	RMDiggs:sjh				LB
DATE ▶	10/10/72				