

September 26, 1972

Docket No. 50-249


Dr. Chester P. Siess  
Chairman, Advisory Committee  
on Reactor Safeguards  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Dr. Siess:


Sixteen (16) copies of the following are transmitted for the  
Committee's  
information:

Letter from Commonwealth Edison Company dated September 20,  
1972, reporting that a reactor protection system limit  
switch on the #4 turbine control valve was found to be  
inoperable contrary to the requirements of the Dresden  
Unit 3 Technical Specifications.

TWX from Commonwealth Edison Company dated September 25,  
1972, concerning the high flow switches on the Dresden  
Unit 3 isolation condenser being out of calibration.

 Distribution  
Docket File  
Branch Reading

Sincerely,

  
Donald J. Skovholt  
Assistant Director for  
Operating Reactors  
Directorate of Licensing

Inclosures:  
As stated

*RWS*

OFFICE ▶	L:OR <i>LRD</i>				
SURNAME ▶	RMDiggs:sjh				
DATE ▶	9/26/72				