

May 3, 1972

Docket Nos. 50-237  
and 50-249

Dr. Chester P. Siess  
Chairman, Advisory Committee  
on Reactor Safeguards  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Dr. Siess:

copies of the following are transmitted for the  
Committee's  
Sixteen (16)

information:

Letter from Commonwealth Edison Company dated April 25,  
1972, reporting a condition relating to a switching  
problem at Dresden Units 2 and 3 which rendered a  
standby gas train, a standby liquid control pump, and  
a core spray system inoperable.

Distribution

- Docket File
- Branch Reading

Sincerely,

Donald J. Skovholt  
Assistant Director  
for Reactor Operations  
Division of Reactor Licensing

Enclosures:  
As stated

LB

OFFICE ▶	DRL				
SURNAME ▶	RMDiggs:sjh				
DATE ▶	5/3/72				