

March 23, 1972

Docket No. 50-249

Dr. Chester P. Siess
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Dr. Siess:


copies of the following are transmitted for the

Sixteen (16)
Committee's

information:

Letter from Commonwealth Edison Company dated March 17,
1972, reporting a wiring error found in the logic
circuitry of the Low Pressure Coolant Injection System
of Dresden Nuclear Power Station Unit No. 3.

Sincerely,



Donald J. Skovholt
Assistant Director
for Reactor Operations
Division of Reactor Licensing

Distribution

Docket File
 Branch Reading
 MGroff, DRL

Enclosures:
As stated

OFFICE ▶

DRL

SURNAME ▶

RMD
eggs: sjh

DATE ▶

3/23/72