

# Docket File

DISTRIBUTION:  
Docket File  
BWR-2 File  
R. Muranaka  
J. Riesland  
H. Gearin

Docket Nos. 50-237  
and 50-249

JAN 20 1972

Dr. Chester P. Siess  
Chairman, Advisory Committee  
on Reactor Safeguards  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Dr. Siess:

Sixteen copies of the following are transmitted for the information  
of the Committee:

Commonwealth Edison Company

C-E letter, dated January 5, 1972, reporting a problem  
with a main steam line hi-flow isolation switch - Dresden  
Unit 2;

C-E letter, dated January 7, 1972, reporting a problem  
with the mechanical vacuum pump suction valve - Dresden  
Unit 3.

Sincerely,

*151 Stolz*

Roger S. Boyd, Assistant Director  
Division of Reactor Licensing

Enclosures:  
As stated

OFFICE ▶	DRL: BWR: LA	DRL: BWR-2				
SURNAME ▶	<i>H. Gearin</i> :vv	<i>R. L. Tedesco</i>				
DATE ▶	1/18/72	1/19/72				